

**Williamsville CSD**

**Locations of Water Test Samples Greater than 15 ppb**

**NOTE: Fixture replacement is being prioritized by our facility staff and is occurring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.**

<b>Maple East</b>								
Location	Boiler Room Sample	Boiler Room Eyewash	Girl's ShBathroom Sink	42 Classroom Sink	29 Classroom Sink # 3	22 Classroom Sink	Library Office Sink	
Test results	18.10	47.40	1220.00	16.20	52.30	17.30	22.30	
Remediation	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	
Results	12.10	1.99	3.55	10.90	14.90	9.70	2.78	
Back in use	9/29/2021	9/29/2021	9/29/2021	9/29/2021	9/29/2021	9/29/2021	9/29/2021	
Location								
Test results								
Remediation								
Results								
Results								
Back in use								