

**Williamsville CSD**

**Locations of Water Test Samples Greater than 15 ppb**

**NOTE: Fixture replacement is being prioritized by our facility staff and is occurring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.**

<b>Maple West</b>								
Location	109 Classroom Sink # 1	Library Office Sink	102 Classroom Sink	Boiler Room Eyewash	Boiler Room Sample	102 Classroom Sink # 2	101 Classroom Sink # 2	Kitchen Pot Filler
Test results	15.40	18.10	16.20	200.00	15.80	22.40	76.00	28.30
Remediation	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing
Results	14.70	18.90	17.30	67.80	43.60	16.70	16.10	5.65
Test results								
Back in use	9/29/2021							9/29/2021
Location								
Test results								
Remediation								
Results								
Results								
Back in use								