

Williamsville CSD

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occurring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

North high								
Location	Boiler Room Source	Conference Room Sink # 1	itchen Dish room Sink # 2	Mens Lav by C-108 Sink # 3	Room C-108 Sink # 1	Room C-108 Sink # 2	Room C-105 Sink # 1	Room C-152 Sink # 1
Test results	23.5	21.3	21.9	21.4	24.6	17.1	53.6	19.2
Remediation	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing
Results	ND	2.86	11.5	10.8	26.9	18.4	4.87	5.01
Back in use	9/29/2021	9/29/2021	9/29/2021	9/29/2021			9/29/2021	9/29/2021
Location	Room C-162 Sink # 2	Mens Lav by C-130 Sink # 1	Mens Lav by C-130 Sink # 2	Mens Lav by C-130 Sink # 3	1st Floor Coaches Office Sink	Pump Room Eye Wash		
Test results	92.2	28	16.2	15.7	305	30.4		
Remediation	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing		
Test results	30.4	16.9	15.5	264	13.7	23.2		
Back in use					9/29/2021			
Location								
Test results								
Remediation								
Back in use								
Location								
Test results								
Remediation								
Results								
Back in use								
Location								
Test results								
Remediation								
Back in use								