Williamsville CSD

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occuring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

Heim middle								
Location	Room D6 Sink # 1	oys Locker Room Sink # 1	Room C-13 Eye Wash	Room C-11 Eyewash	Room A-11 Eyewash	ens Lav by Aud Sink # 2	by Steamer in Kitchen	Boiler Room Eye Wash
Test results	28.8	16.7	51.7	93.9	232	19	119	46.9
Remediation								
Back in svc.								
Location								
Test results								
Remediation								
Back in svc.								
Location								
Test results								
Remediation								
Results								
Back in svc.								
Location								
Test results								
Remediation								
Results								
Back in svc.								
Location								
Test results								
Remediation								
Back in svc.								
Location								
Test results								
Remediation								
Back in svc.								