

Williamsville CSD

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occurring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

Heim								
Location	Room 142 Sink	Room 146 Sink						
Test results	16.60	16.80						
Remediation								
Results								
Results 2								
Back in use								
Location								
Test results								
Remediation								
Results								
Results								
Results								
Back in use								