Williamsville CSD

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occuring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

South high								
Location	Room 134 Sink # 1	Room 134 Sink # 2	Room E-6 Sink	pm 129 P Dark Room Sink	Room 129 D Sink # 1	Room 129 D Sink # 2	Room 129 D Sink # 3	Room 129 D Sink # 4
Test results	23.5	31.3	18.6	15.8	59.4	16.1	16.8	34
Test results2								
Remediation								
Back in use								
Location	Coaches Girls Off Shower							
Test results	193							
Remediation								
Back in use								